

Service Bulletin

Number: 6010003

2,000 Watt Inverter Carburetor Replacement

This bulletin covers the following Champion Power Equipment models:

2,000 watt Champion Inverters – All Models

Note: Read instructions completely before performing service.

- 1. Remove handle bolts in four corner pockets with a 10mm socket.
- 2. Remove Phillips head screw inside of fuel knob and remove knob.
- 3. Remove gas cap and then lift top panel off. It will snap off easily. Remember to replace gas cap after top panel is removed. Be sure gas cap vent is in OFF position.
- 4. Remove three 7mm tank bolts. Lift tank and hang over backside panel with hose connected.
- 5. Loosen the choke cable from the choke pinch bolt.



6. Loosen the choke cable bracket then <u>pull choke cable out and away from carburetor</u>.





Service Bulletin

Number: 6010003

7. Detach smaller rubber air hose from the air filter assembly. Followed by the two 10mm nuts.



8. Twist the larger air cleaner tube away from the carburetor body and slide the carburetor off the two engine studs.



9. Replace carburetor gaskets and carburetor. Reverse the previous steps to complete install.

If you have any questions, please contact Champion Power Equipment:

Champion Power Equipment, Inc. 12039 Smith Ave.

Santa Fe Springs, CA 90670

Phone: 1-877-338-0999

Email: tech@championpowerequipment.com