

Move-in / Move-out Condition Report

Inspected on February 2, 2021 1:18 PM

| Report Created on February 2, 2021 5:06 PM


Entry

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Excellent condition	
Check Blinds	Condition: Excellent condition	
Check Window Screens	Condition: Present, no issues	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector Presence	Presence: Not present	


Photos



Overview Photos (1/4)
02/02/2021 1:18 PM



Overview Photos (2/4)
02/02/2021 1:18 PM



Overview Photos (3/4)
02/02/2021 1:18 PM



Overview Photos (4/4)
02/02/2021 1:18 PM




Door(s) (1/2)
02/02/2021 1:19 PM



Door(s) (2/2)
02/02/2021 1:19 PM



Walls & Windows (1/4)
02/02/2021 1:19 PM



Walls & Windows (2/4)
02/02/2021 1:19 PM



Walls & Windows (3/4)
02/02/2021 1:19 PM



Walls & Windows (4/4)
02/02/2021 1:19 PM



Check Blinds (1/2)
02/02/2021 1:20 PM



Check Blinds (2/2)
02/02/2021 1:20 PM



Floor
02/02/2021 1:20 PM



Ceiling
02/02/2021 1:20 PM

Hallway / Stairs

Items	Values	Notes
Walls & Windows	Condition: Excellent condition	
Check Blinds	Condition: Not Present	
Check Window Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector Presence	Presence: Not present	
Closet / Cupboards / etc	Condition: Excellent condition	

Photos



Overview Photos (1/4)
02/02/2021 1:21 PM



Overview Photos (2/4)
02/02/2021 1:21 PM



Overview Photos (3/4)
02/02/2021 1:21 PM



Overview Photos (4/4)
02/02/2021 1:53 PM



Walls & Windows (1/3)
02/02/2021 1:22 PM



Walls & Windows (2/3)
02/02/2021 1:22 PM



Walls & Windows (3/3)
02/02/2021 1:22 PM



Floor (1/2)
02/02/2021 1:22 PM



Floor (2/2)
02/02/2021 1:22 PM



Ceiling (1/2)
02/02/2021 1:22 PM



Ceiling (2/2)
02/02/2021 1:23 PM



Closet / Cupboards / etc (1/3)
02/02/2021 1:23 PM



Closet / Cupboards / etc (2/3)
02/02/2021 1:23 PM



Closet / Cupboards / etc (3/3)
02/02/2021 1:23 PM

Living / Dining Room

Items	Values	Notes
Walls & Windows	Condition: Excellent condition	
Check Blinds	Condition: Excellent condition	
Check Window Screens	Condition: Present, no issues	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector Presence	Presence: Present	
Closet / Cupboards / etc	Condition: Excellent condition	

Photos



Overview Photos (1/10)
02/02/2021 1:24 PM




Overview Photos (2/10)
02/02/2021 1:24 PM



Overview Photos (3/10)
02/02/2021 1:24 PM



Overview Photos (4/10)
02/02/2021 1:24 PM



Overview Photos (5/10)
02/02/2021 1:24 PM



Overview Photos (6/10)
02/02/2021 1:24 PM



Overview Photos (7/10)
02/02/2021 1:24 PM




Overview Photos (8/10)
02/02/2021 1:24 PM



Overview Photos (9/10)
02/02/2021 1:24 PM



Overview Photos (10/10)
02/02/2021 1:24 PM




Walls & Windows (1/5)
02/02/2021 1:25 PM



Walls & Windows (2/5)
02/02/2021 1:25 PM



Walls & Windows (3/5)
02/02/2021 1:25 PM



Walls & Windows (4/5)
02/02/2021 1:25 PM



Walls & Windows (5/5)
02/02/2021 1:25 PM



Check Blinds
02/02/2021 1:25 PM



Floor (1/6)
02/02/2021 1:26 PM



Floor (2/6)
02/02/2021 1:26 PM



Floor (3/6)
02/02/2021 1:26 PM



Floor (4/6)
02/02/2021 1:26 PM



Floor (5/6)
02/02/2021 1:26 PM



Floor (6/6)
02/02/2021 1:26 PM



Ceiling (1/4)
02/02/2021 1:26 PM



Ceiling (2/4)
02/02/2021 1:26 PM



Ceiling (3/4)
02/02/2021 1:26 PM



Ceiling (4/4)
02/02/2021 1:26 PM



Smoke / CO detector Presence
02/02/2021 1:27 PM



Closet / Cupboards / etc (1/4)
02/02/2021 1:27 PM



Closet / Cupboards / etc (2/4)
02/02/2021 1:27 PM



Closet / Cupboards / etc (3/4)
02/02/2021 1:27 PM



Closet / Cupboards / etc (4/4)
02/02/2021 1:27 PM

Kitchen

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Good - some wear and tear	Scuff marks on wall near garage door
Check Blinds	Condition: Not Present	
Check Window Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector Presence	Presence: Not present	
Kitchen cabinets / Closet / etc	Condition: Good - some wear and tear	Minor scuff marks on cabinet drawers
Kitchen cabinets / Closet / etc (2)	Condition: Good - some wear and tear	Cabinet interiors are worn
Counter Tops	Condition: Excellent condition	
Sink & Underneath Sink	Condition: Good - some wear and tear	Minor stains
Refrigerator	Condition: Excellent condition	
Oven / Stove / Range	Condition: Excellent condition	
Microwave	Condition: Excellent condition	
Dishwasher	Condition: Excellent condition	
Other Appliances	Condition: Excellent condition	

Photos



Overview Photos (1/6)
02/02/2021 1:28 PM



Overview Photos (2/6)
02/02/2021 1:28 PM



Overview Photos (3/6)
02/02/2021 1:28 PM



Overview Photos (4/6)
02/02/2021 1:28 PM



Overview Photos (5/6)
02/02/2021 1:28 PM



Overview Photos (6/6)
02/02/2021 1:28 PM



Door(s) (1/2)
02/02/2021 1:29 PM



Door(s) (2/2)
02/02/2021 1:29 PM



Walls & Windows (1/2)
02/02/2021 1:29 PM



Walls & Windows (2/2)
02/02/2021 1:29 PM



Floor (1/3)
02/02/2021 1:30 PM



Floor (2/3)
02/02/2021 1:30 PM



Floor (3/3)
02/02/2021 1:30 PM



Ceiling (1/2)
02/02/2021 1:30 PM



Ceiling (2/2)
02/02/2021 1:30 PM



Kitchen cabinets / Closet / etc (1/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (2/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (3/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (4/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (5/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (6/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (7/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (8/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (9/11)
02/02/2021 1:31 PM



Kitchen cabinets / Closet / etc (10/11)
02/02/2021 1:34 PM



Kitchen cabinets / Closet / etc (11/11)
02/02/2021 1:34 PM



Kitchen cabinets / Closet / etc (2) (1/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (2/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (3/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (4/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (5/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (6/16)
02/02/2021 1:32 PM



Kitchen cabinets / Closet / etc (2) (7/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (8/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (9/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (10/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (11/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (12/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (13/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (14/16)

02/02/2021 1:33 PM



Kitchen cabinets / Closet / etc (2) (15/16)

02/02/2021 1:34 PM



Kitchen cabinets / Closet / etc (2) (16/16)

02/02/2021 1:34 PM



Counter Tops (1/5)

02/02/2021 1:35 PM



Counter Tops (2/5)

02/02/2021 1:35 PM



Counter Tops (3/5)

02/02/2021 1:35 PM



Counter Tops (4/5)

02/02/2021 1:35 PM



Counter Tops (5/5)

02/02/2021 1:35 PM



Sink & Underneath Sink (1/2)

02/02/2021 1:35 PM



Sink & Underneath Sink (2/2)
02/02/2021 1:35 PM



Refrigerator (1/5)
02/02/2021 1:36 PM



Refrigerator (2/5)
02/02/2021 1:36 PM



Refrigerator (3/5)
02/02/2021 1:36 PM



Refrigerator (4/5)
02/02/2021 1:36 PM



Refrigerator (5/5)
02/02/2021 1:36 PM



Oven / Stove / Range (1/2)
02/02/2021 1:36 PM



Oven / Stove / Range (2/2)
02/02/2021 1:36 PM



Microwave (1/2)
02/02/2021 1:37 PM



Microwave (2/2)
02/02/2021 1:37 PM



Dishwasher (1/2)
02/02/2021 1:37 PM



Dishwasher (2/2)
02/02/2021 1:37 PM



Other Appliances
02/02/2021 1:37 PM

Bathroom

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Excellent condition	

Items	Values	Notes
Check Blinds	Condition: Not Present	
Check Window Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Vanity / Cabinets / etc	Condition: Not Present	
Counter Tops	Condition: Not Present	
Sink & Underneath Sink	Condition: Excellent condition	
Toilet	Condition: Excellent condition	

Photos



Overview Photos (1/4)
02/02/2021 1:37 PM



Overview Photos (2/4)
02/02/2021 1:38 PM



Overview Photos (3/4)
02/02/2021 1:38 PM



Overview Photos (4/4)
02/02/2021 1:38 PM



Door(s) (1/4)
02/02/2021 1:38 PM




Door(s) (2/4)
02/02/2021 1:38 PM



Door(s) (3/4)
02/02/2021 1:38 PM




Door(s) (4/4)
02/02/2021 1:38 PM



Walls & Windows (1/6)
02/02/2021 1:38 PM



Walls & Windows (2/6)
02/02/2021 1:38 PM



Walls & Windows (3/6)
02/02/2021 1:38 PM



Walls & Windows (4/6)
02/02/2021 1:38 PM



Walls & Windows (5/6)
02/02/2021 1:39 PM



Walls & Windows (6/6)
02/02/2021 1:39 PM



Floor (1/2)
02/02/2021 1:39 PM



Floor (2/2)
02/02/2021 1:39 PM



Ceiling (1/2)
02/02/2021 1:39 PM



Ceiling (2/2)
02/02/2021 1:39 PM



Sink & Underneath Sink
02/02/2021 1:39 PM



Toilet (1/2)
02/02/2021 1:40 PM



Toilet (2/2)
02/02/2021 1:40 PM

Laundry room

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Good - some wear and tear	Walls are dirty
Check Blinds	Condition: Not Present	
Check Windows Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector	Presence: Not present	

Photos



Overview Photos (1/4)
02/02/2021 1:40 PM



Overview Photos (2/4)
02/02/2021 1:40 PM




Overview Photos (3/4)
02/02/2021 1:41 PM



Overview Photos (4/4)
02/02/2021 1:41 PM



Door(s) (1/4)
02/02/2021 1:41 PM



Door(s) (2/4)
02/02/2021 1:41 PM



Door(s) (3/4)
02/02/2021 1:41 PM



Door(s) (4/4)
02/02/2021 1:41 PM



Walls & Windows (1/4)
02/02/2021 1:41 PM



Walls & Windows (2/4)
02/02/2021 1:41 PM



Walls & Windows (3/4)
02/02/2021 1:42 PM



Walls & Windows (4/4)
02/02/2021 1:42 PM



Floor (1/2)
02/02/2021 1:42 PM



Floor (2/2)
02/02/2021 1:42 PM



Ceiling (1/2)
02/02/2021 1:42 PM



Ceiling (2/2)
02/02/2021 1:42 PM

Bedroom

Items	Values	Notes
Door(s)	Condition: Good - some wear and tear	Minor scuff on door
Walls & Windows	Condition: Good - some wear and tear	Nail holes and wall hanger still in drywall
Check Blinds	Condition: Excellent condition	
Check Window Screens	Condition: Present, no issues	
Floor	Condition: Excellent condition	
Ceiling	Condition: Good - some wear and tear	Glow in dark stars on ceiling and minor scuffs
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector Presence	Presence: Present	
Closet / Cupboards / etc	Condition: Excellent condition	

Photos



Overview Photos (1/6)
02/02/2021 1:43 PM



Overview Photos (2/6)
02/02/2021 1:43 PM



Overview Photos (3/6)
02/02/2021 1:43 PM



Overview Photos (4/6)
02/02/2021 1:43 PM



Overview Photos (5/6)
02/02/2021 1:44 PM



Overview Photos (6/6)
02/02/2021 1:44 PM



Door(s) (1/5)
02/02/2021 1:44 PM



Door(s) (2/5)
02/02/2021 1:44 PM



Door(s) (3/5)
02/02/2021 1:44 PM



Door(s) (4/5)
02/02/2021 1:44 PM



Door(s) (5/5)
02/02/2021 1:44 PM



Walls & Windows (1/4)
02/02/2021 1:44 PM



Walls & Windows (2/4)
02/02/2021 1:45 PM



Walls & Windows (3/4)
02/02/2021 1:45 PM



Walls & Windows (4/4)
02/02/2021 1:45 PM



Check Blinds
02/02/2021 1:45 PM



Floor (1/3)
02/02/2021 1:46 PM



Floor (2/3)
02/02/2021 1:46 PM




Floor (3/3)
02/02/2021 1:46 PM



Ceiling (1/4)
02/02/2021 1:46 PM



Ceiling (2/4)
02/02/2021 1:46 PM



Ceiling (3/4)
02/02/2021 1:46 PM



Ceiling (4/4)
02/02/2021 1:47 PM



Smoke / CO detector Presence
02/02/2021 1:47 PM



Closet / Cupboards / etc (1/4)
02/02/2021 1:47 PM



Closet / Cupboards / etc (2/4)
02/02/2021 1:47 PM



Closet / Cupboards / etc (3/4)
02/02/2021 1:47 PM



Closet / Cupboards / etc (4/4)
02/02/2021 1:47 PM

Bathroom 2

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Excellent condition	
Check Blinds	Condition: Not Present	
Check Window Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Vanity / Cabinets / etc	Condition: Excellent condition	
Counter Tops	Condition: Excellent condition	
Sink & Underneath Sink	Condition: Good - some wear and tear	Water stains underneath and paint stains on sink
Shower / Tub	Condition: Excellent condition	
Toilet	Condition: Excellent condition	

Photos



Overview Photos (1/7)
02/02/2021 1:48 PM



Overview Photos (2/7)
02/02/2021 1:48 PM



Overview Photos (3/7)
02/02/2021 1:48 PM




Overview Photos (4/7)
02/02/2021 1:48 PM



Overview Photos (5/7)
02/02/2021 1:48 PM



Overview Photos (6/7)
02/02/2021 1:49 PM



Overview Photos (7/7)
02/02/2021 1:49 PM



Door(s) (1/4)
02/02/2021 1:49 PM



Door(s) (2/4)
02/02/2021 1:49 PM



Door(s) (3/4)
02/02/2021 1:50 PM



Door(s) (4/4)
02/02/2021 1:50 PM



Walls & Windows (1/7)
02/02/2021 1:50 PM



Walls & Windows (2/7)
02/02/2021 1:50 PM



Walls & Windows (3/7)
02/02/2021 1:50 PM




Walls & Windows (4/7)
02/02/2021 1:50 PM



Walls & Windows (5/7)
02/02/2021 1:50 PM



Walls & Windows (6/7)
02/02/2021 1:51 PM



Walls & Windows (7/7)
02/02/2021 1:51 PM



Floor
02/02/2021 1:51 PM



Ceiling (1/2)
02/02/2021 1:51 PM



Ceiling (2/2)
02/02/2021 1:51 PM



Vanity / Cabinets / etc
02/02/2021 1:52 PM



Counter Tops
02/02/2021 1:52 PM



Sink & Underneath Sink (1/2)
02/02/2021 1:52 PM



Sink & Underneath Sink (2/2)
02/02/2021 1:52 PM



Shower / Tub (1/4)
02/02/2021 1:52 PM



Shower / Tub (2/4)
02/02/2021 1:52 PM



Shower / Tub (3/4)
02/02/2021 1:52 PM



Shower / Tub (4/4)
02/02/2021 1:52 PM



Toilet (1/2)
02/02/2021 1:53 PM



Toilet (2/2)
02/02/2021 1:53 PM

Bonus area

Items	Values	Notes
Walls & Windows	Condition: Good - some wear and tear	Minor scuff marks on walls
Check Windows Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector	Presence: Present	

Photos



Overview Photos (1/4)
02/02/2021 1:53 PM




Overview Photos (2/4)
02/02/2021 1:54 PM



Overview Photos (3/4)
02/02/2021 1:54 PM



Overview Photos (4/4)
02/02/2021 1:54 PM



Walls & Windows (1/3)
02/02/2021 1:54 PM



Walls & Windows (2/3)
02/02/2021 1:54 PM



Walls & Windows (3/3)
02/02/2021 1:54 PM



Floor
02/02/2021 1:55 PM



Ceiling
02/02/2021 1:55 PM



Smoke / CO detector
02/02/2021 1:55 PM

Bedroom 2

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Excellent condition	
Check Blinds	Condition: Excellent condition	
Check Window Screens	Condition: Present, no issues	
Floor	Condition: Excellent condition	
Ceiling	Condition: Good - some wear and tear	Water stain on ceiling
Over Head Lights	Condition: Present, no issues	

Items	Values	Notes
Smoke / CO detector Presence	Presence: Present	
Closet / Cupboards / etc	Condition: Good - some wear and tear	Scuff marks on walls

Photos



Overview Photos (1/7)
02/02/2021 1:55 PM



Overview Photos (2/7)
02/02/2021 1:55 PM



Overview Photos (3/7)
02/02/2021 1:56 PM



Overview Photos (4/7)
02/02/2021 1:56 PM



Overview Photos (5/7)
02/02/2021 1:56 PM




Overview Photos (6/7)
02/02/2021 1:56 PM



Overview Photos (7/7)
02/02/2021 1:56 PM



Door(s) (1/4)
02/02/2021 1:56 PM



Door(s) (2/4)
02/02/2021 1:56 PM




Door(s) (3/4)
02/02/2021 1:56 PM



Door(s) (4/4)
02/02/2021 1:56 PM



Walls & Windows (1/4)
02/02/2021 1:56 PM



Walls & Windows (2/4)
02/02/2021 1:57 PM



Walls & Windows (3/4)
02/02/2021 1:57 PM



Walls & Windows (4/4)
02/02/2021 1:57 PM



Check Blinds (1/2)
02/02/2021 1:57 PM



Check Blinds (2/2)
02/02/2021 1:57 PM



Floor (1/4)
02/02/2021 1:57 PM




Floor (2/4)
02/02/2021 1:58 PM




Floor (3/4)
02/02/2021 1:58 PM



Floor (4/4)
02/02/2021 1:58 PM



Ceiling (1/3)
02/02/2021 1:58 PM



Ceiling (2/3)
02/02/2021 1:58 PM



Ceiling (3/3)
02/02/2021 1:58 PM



Smoke / CO detector Presence
02/02/2021 1:58 PM



Closet / Cupboards / etc (1/6)
02/02/2021 1:59 PM



Closet / Cupboards / etc (2/6)
02/02/2021 1:59 PM



Closet / Cupboards / etc (3/6)
02/02/2021 1:59 PM



Closet / Cupboards / etc (4/6)
02/02/2021 1:59 PM



Closet / Cupboards / etc (5/6)
02/02/2021 1:59 PM



Closet / Cupboards / etc (6/6)
02/02/2021 1:59 PM

Bathroom 3

Items	Values	Notes
Door(s)	Condition: Excellent condition	
Walls & Windows	Condition: Excellent condition	

Items	Values	Notes
Check Blinds	Condition: Not Present	
Check Window Screens	Condition: Not present	
Floor	Condition: Excellent condition	
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Vanity / Cabinets / etc	Condition: Excellent condition	
Counter Tops	Condition: Excellent condition	
Sink & Underneath Sink	Condition: Excellent condition	
Shower / Tub	Condition: Excellent condition	
Toilet	Condition: Excellent condition	

Photos



Overview Photos (1/6)
02/02/2021 1:59 PM



Overview Photos (2/6)
02/02/2021 1:59 PM



Overview Photos (3/6)
02/02/2021 2:00 PM



Overview Photos (4/6)
02/02/2021 2:00 PM



Overview Photos (5/6)
02/02/2021 2:00 PM



Overview Photos (6/6)
02/02/2021 2:00 PM



Door(s) (1/4)
02/02/2021 2:00 PM



Door(s) (2/4)
02/02/2021 2:00 PM



Door(s) (3/4)
02/02/2021 2:00 PM



Door(s) (4/4)
02/02/2021 2:00 PM



Walls & Windows (1/5)
02/02/2021 2:00 PM



Walls & Windows (2/5)
02/02/2021 2:00 PM



Walls & Windows (3/5)
02/02/2021 2:01 PM



Walls & Windows (4/5)
02/02/2021 2:01 PM



Walls & Windows (5/5)
02/02/2021 2:01 PM




Floor (1/3)
02/02/2021 2:01 PM



Floor (2/3)
02/02/2021 2:01 PM



Floor (3/3)
02/02/2021 2:01 PM



Ceiling (1/4)
02/02/2021 2:01 PM



Ceiling (2/4)
02/02/2021 2:01 PM



Ceiling (3/4)
02/02/2021 2:02 PM



Ceiling (4/4)
02/02/2021 2:02 PM



Vanity / Cabinets / etc (1/5)
02/02/2021 2:02 PM



Vanity / Cabinets / etc (2/5)
02/02/2021 2:02 PM



Vanity / Cabinets / etc (3/5)
02/02/2021 2:02 PM



Vanity / Cabinets / etc (4/5)
02/02/2021 2:02 PM



Vanity / Cabinets / etc (5/5)
02/02/2021 2:02 PM



Counter Tops (1/2)
02/02/2021 2:03 PM



Counter Tops (2/2)
02/02/2021 2:03 PM



Sink & Underneath Sink (1/4)
02/02/2021 2:03 PM



Sink & Underneath Sink (2/4)
02/02/2021 2:03 PM



Sink & Underneath Sink (3/4)
02/02/2021 2:03 PM



Sink & Underneath Sink (4/4)
02/02/2021 2:03 PM



Shower / Tub (1/5)
02/02/2021 2:03 PM



Shower / Tub (2/5)
02/02/2021 2:03 PM



Shower / Tub (3/5)
02/02/2021 2:03 PM



Shower / Tub (4/5)
02/02/2021 2:03 PM



Shower / Tub (5/5)
02/02/2021 2:03 PM



Toilet (1/2)
02/02/2021 2:04 PM



Toilet (2/2)
02/02/2021 2:04 PM

Garage

Items	Values	Notes
Door(s)	Condition: Good - some wear and tear	Minor scuff marks
Walls & Windows	Condition: Good - some wear and tear	Nail holes in walls and some parts of wall dirty
Check Window Screens	Condition: Not present	
Floor	Condition: Good - some wear and tear	Some stains on floor
Ceiling	Condition: Excellent condition	
Over Head Lights	Condition: Present, no issues	
Smoke / CO detector	Presence: Not present	
Furnace	Presence: Not present	Furnace is in the attic

Items	Values	Notes
Water heater	Presence: Present	


Photos



Overview Photos (1/7)
02/02/2021 2:04 PM



Overview Photos (2/7)
02/02/2021 2:04 PM



Overview Photos (3/7)
02/02/2021 2:04 PM



Overview Photos (4/7)
02/02/2021 2:05 PM



Overview Photos (5/7)
02/02/2021 2:05 PM



Overview Photos (6/7)
02/02/2021 2:05 PM



Overview Photos (7/7)
02/02/2021 2:05 PM



Door(s) (1/3)
02/02/2021 2:05 PM



Door(s) (2/3)
02/02/2021 2:05 PM



Door(s) (3/3)
02/02/2021 2:05 PM



Walls & Windows (1/6)
02/02/2021 2:06 PM



Walls & Windows (2/6)
02/02/2021 2:06 PM



Walls & Windows (3/6)
02/02/2021 2:06 PM



Walls & Windows (4/6)
02/02/2021 2:06 PM



Walls & Windows (5/6)
02/02/2021 2:06 PM



Walls & Windows (6/6)
02/02/2021 2:06 PM



Floor (1/4)
02/02/2021 2:06 PM



Floor (2/4)
02/02/2021 2:07 PM



Floor (3/4)
02/02/2021 2:07 PM



Floor (4/4)
02/02/2021 2:07 PM



Ceiling (1/3)
02/02/2021 2:07 PM



Ceiling (2/3)
02/02/2021 2:07 PM



Ceiling (3/3)
02/02/2021 2:07 PM



Water heater (1/5)
02/02/2021 2:12 PM



Water heater (2/5)
02/02/2021 2:12 PM



Water heater (3/5)
02/02/2021 2:12 PM



Water heater (4/5)
02/02/2021 2:12 PM



Water heater (5/5)
02/02/2021 2:12 PM

Exterior

Items	Values	Notes
Landscaping	Condition: Excellent condition	
Building Exterior	Condition: Excellent condition	

Photos



Overview Photos (1/8)
02/02/2021 2:08 PM



Overview Photos (2/8)
02/02/2021 2:08 PM



Overview Photos (3/8)
02/02/2021 2:08 PM



Overview Photos (4/8)
02/02/2021 2:08 PM



Overview Photos (5/8)
02/02/2021 2:09 PM



Overview Photos (6/8)
02/02/2021 2:09 PM




Overview Photos (7/8)
02/02/2021 2:09 PM



Overview Photos (8/8)
02/02/2021 2:09 PM



Landscaping (1/2)
02/02/2021 2:10 PM



Landscaping (2/2)
02/02/2021 2:10 PM



Building Exterior (1/5)
02/02/2021 2:10 PM



Building Exterior (2/5)
02/02/2021 2:10 PM



Building Exterior (3/5)
02/02/2021 2:10 PM



Building Exterior (4/5)
02/02/2021 2:10 PM



Building Exterior (5/5)
02/02/2021 2:10 PM

Odors/Cleanliness/Comments

Items	Values	Notes
Comments on Odors	Odors: Fair	
Property Cleanliness	Condition: Clean	